

## Version 3.6

- Added the ability to choose whether 48V is retained after restarting Scarlett 3rd Generation interfaces.
- Added a "Device" menu to the menu bar, where you can set the "Retain 48V" option.
- Added the ability to change the sample rate from the "Device" menu.

### Scarlett 3rd Gen 18i20 Interfaces:

- Added the ability to change the talkback input source.
- Added the ability to adjust the level of the talkback input source.
- Added the ability to see the level of the talkback input source.
- Included talkback settings in snapshots.
- Added Cmd-T shortcut (Ctrl-T on Windows) for toggling talkback.
- The "Talk" button now greys out at high sample rates and displays a tooltip to indicate that talkback is disabled.

### Firmware updated for the following interfaces:

#### *Scarlett 2nd Gen:*

- 18i20 - Version 1653

#### *Scarlett 3rd Gen:*

- 18i20 - Version 1644

## Windows

### - Updated USB Driver to version 4.65.5. Changes since last main release (4.63.24):

- Fixed an issue that caused some DAWs (namely Studio One, Reason and Sibelius) to expose unsupported buffer size options
- Added multichannel WDM support (surround sound)
- Added option to expose multiple WDM inputs and outputs (Analogue, S/PDIF and Loopback channels)
- Fixed an issue that could cause glitching on systems with some older AMD processors (Phenom-II, FX and Athlon series)
- Fixed an issue that could cause glitching when using more than one ASIO application at the same time
- Renamed "LOCKED" to "SYNCED" to avoid confusion around clock status
- Numerous stability and performance improvements

Notes: the additional WDM input and output channels can be enabled/disabled by clicking the Focusrite Notifier icon in the taskbar and selecting the "Expose/Hide Windows Channels" menu option.

## **Version 3.5**

- Added the ability to change the colour of the good, pre-clipping and clipping stages of the Gain Halos on Scarlett 3rd Generation interfaces.
- Added the ability to preview Gain Halo colours before assigning them.
- Prevented interfaces from appearing in Focusrite Control until they are fully initialised.
- Removed the delay time for tooltips to appear.
- Stability improvements to firmware for Scarlett 2nd Generation 6i6, 18i8, 18i20 interfaces.

### **Windows**

- Changed uninstaller name in the start menu to "Focusrite Control Uninstaller".

### **macOS**

- Added hardened runtime signing flag for improved Catalina support.
- Improved connection behaviour when waking Mac from sleep for Scarlett 2nd Generation interfaces.

### Firmware updated for the following interfaces:

#### *Scarlett 2nd Gen:*

- 6i6 - Version 1583
- 18i8 - Version 1583
- 18i20 - Version 1583

#### *Scarlett 3rd Gen:*

- Solo - Version 1605
- 2i2 - Version 1605
- 4i4 - Version 1605
- 8i6 - Version 1605
- 18i8 - Version 1605