Focusrite Control 3.5.0 – Release Notes

- Added the ability to change the colour of the good, pre-clipping and clipping stages of the Gain Halos on Scarlett 3rd Generation interfaces.
- Added the ability to preview Gain Halo colours before assigning them.
- Prevented interfaces from appearing in Focusrite Control until they are fully initialised.
- Removed the delay time for tool tips to appear.
- Stability improvements to firmware for Scarlett 2nd Generation 6i6, 18i8, 18i20 interfaces.

Windows
- Changed uninstaller name in the start menu to "Focusrite Control Uninstaller".

macOS
- Added hardened runtime signing flag for improved Catalina support.
- Improved connection behaviour when waking Mac from sleep for Scarlett 2nd Generation interfaces.

Firmware updated for the following interfaces:

Scarlett 2nd Gen:
6i6 - Version 1583
18i8 - Version 1583
18i20 - Version 1583

Scarlett 3rd Gen:
Solo - Version 1605
2i2 - Version 1605
4i4 - Version 1605
8i6 - Version 1605
18i8 - Version 1605